

TRACK INSPECTION REPORTING FORM

me Billard Date 8-5-2013 Page 1 of 1
(Please Print)
Watchman Nelson
Inspected From Hunt Valley To Lutherville W.O Number 1171626

	Exception Chain Marker No.		W.O.	Track	Rail	Switch	Codes		Status	Repair
Item	From	To	Number	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
Item	COMMENTS									

Item	COMMENTS
------	----------

No new defects noted

Track inspection complete

Were Switch in the area of inspection? ☒

Were Switch in the area of Inspected Yes NO

Were all ~~single~~ operating mechanism & connecting rod type switches inside area and operated in each position ?
Yes _____ NO _____

SPECIAL INSPECTION Yes _____ NO

Reason for special Inspection ? _____

Track Inspector Signature

Richard L. Colvard

Supervisory Certification

n 

Quick Reporting (Tr) Bulletins: (1) Go To Reports Start Center Profile Sign Out Help

Find: Select Action

Quick Reporting Specifications

Work Order TEAM ONE - SECT 1: HV/LU - CM 902N TO

Classification

Asset

Alias

Location

Work Location

Work Group

Site

Status

Priority

Work Type

Crew

Warranty Situation Present?

Maintenance Alert? ☐

Work Details

Component

Position

Reason for Repair

Work Accomplished

Part Failure

Parent WO

Telematics Code

Telematics Transaction

GL Account

Total Planned Cost

Total Actual Cost

Repair Limit Amount

Reported By

Reported Date

Asset Details

Primary Meter

Multiple Assets, Locations and CIs Filter

Tasks Filter 1 - 2 of 2

Sequence	Task	Summary	Component	Reason for Repair	Warranty?	Route	Route Stop	Qualifications	Status
10	10	ESTABLISH ON TRACK SAFETY PER RPW	<input type="text"/>	<input type="text"/>	N			NONE	CLOSE
20	20	INSPECT TRACK PER BALT LR STANDARD	<input type="text"/>	<input type="text"/>	N			NONE	CLOSE

Author Materials Tools Failure Reporting

Labor Filter 1 - 2 of 2

Task	Labor	Approved?	Start Date	Start Time	End Time	Regular Hours	Rate	Warranty?	Qualification Met?
	MPOLLARD	<input checked="" type="checkbox"/>	08/05/13	07:00:00	03:00:00 F	8:00	26.29	N	N/A
	RNELSON1	<input checked="" type="checkbox"/>	08/05/13	07:00:00	03:00:00 F	8:00	26.29	N	N/A

Select Labor Select Planned Labor New Row

TRACK INSPECTION REPORTING FORM

ime Pollard

Date 8-6-2013

Page 1 of 1

Watchman (Please Print) Nelson

Inspected From Cold Spring

To Camden yard

W.O Number 1173389
Pennline

Item	Exception Chain Marker No.		W.O.	Track	Rail	Switch	Codes		Status	Repair
	From	To	Number	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										

Item COMMENTS

No new defects noted.

Track inspection complete

Were Switch in the area of Inspected Yes ✓ NO

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?
Yes NO

SPECIAL INSPECTION Yes NO ✓

Reason for special Inspection ?

Track Inspector Signature

Michael L. Pollard

Supervisory Certification

Quick Reporting (Tr) Bulletins: (1) Go To Reports Start Center Profile Sign Out Help

Find: Select Action

Quick Reporting Specifications

Work Order	1173389	TEAM ONE - SECT 3: CS/CY/PENN - CM 23	Site	LTRAIL
Classification	MTA \ LTRAIL	MTA - LTRAIL	Status	COMP
Asset			Priority	1
Alias			Work Type*	PM
Location	CHAIN_MARK	LT Rail Chain Markers	Crew	DAY-A
Work Location			Warranty Situation Present?	N
Work Group*	MTA527		Maintenance Alert?	

Work Details

Component		Total Planned Cost	0.00
Position		Total Actual Cost	420.64
Reason for Repair		Repair Limit Amount	
Work Accomplished		Reported By	MTACRON
Part Failure		Reported Date	08/04/13 12:22:35 AM
Parent WO			
Telematics Code			
Telematics Transaction			
GL Account	J05-####-052		

Asset Details

Primary Meter

Multiple Assets, Locations and CIs Filter Download

Tasks Filter 1 - 2 of 2 Download

Sequence	Task	Summary	Component	Reason for Repair	Warranty?	Route	Route Stop	Qualifications	Status
10	10	ESTABLISH ON TRACK SAFETY PER RPW			N			NONE	COMP
20	20	INSPECT TRACK PER BALT LR STANDAR			N			NONE	COMP

Labor Materials Tools Failure Reporting

Labor Filter 1 - 2 of 2 Download

Task	Labor	Approved?	Start Date	Start Time	End Time	Regular Hours	Rate	Warranty?	Qualification Met?
	MPOLLARD	<input checked="" type="checkbox"/>	08/06/13	07:00:00	03:00:00	8:00	26.29	N	N/A
	RNELSON1	<input checked="" type="checkbox"/>	08/06/13	07:00:00	03:00:00	8:00	26.29	N	N/A

Select Labor Select Planned Labor New Row

TRACK INSPECTION REPORTING FORM

ame G. LAM

Date 8-6-2013

Page 1 of 1

(Please Print)

Watchman Brock meyer

Inspected From

LV ✓

To

CS

W.O Number .

1173294

	Exception Chain Marker No.		W.O.	Track	Rail	Switch	Codes		Status	Repair
Item	From	To	Number	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
Item	COMMENTS									

Item	COMMENTS
------	----------

Riding inspections due to inclement weather

Were Switch in the area of Inspected Yes ☒ NO

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?

Yes _____ NO ☒

SPECIAL INSPECTION Yes_____ NO ✓

Reason for special Inspection ?

Track Inspector Signature

Supervisory Certification

ion 

Quick Reporting (Tr) Bulletins: (1) Go To Reports Start Center Profile Sign Out Help

Find: Select Action

Quick Reporting Specifications

Work Order	1173294	TEAM TWO - SECT 2: LU/CS - CM 586N TO	Site	LTRAIL
Classification	MTA \ LTRAIL	MTA - LTRAIL	Status	COMP
Asset			Priority	1
Alias			Work Type	PM
Location	CHAIN_MARK	LT Rail Chain Markers	Crew	
Work Location			Warranty Situation Present?	N
Work Group	MTA527		Maintenance Alert?	<input type="checkbox"/>

Work Details

Component		Total Planned Cost	0.00
Position		Total Actual Cost	427.68
Reason for Repair		Repair Limit Amount	
Work Accomplished		Reported By	MTACRON
Part Failure		Reported Date	08/04/13 12:16:31 AM
Parent WO			
Telematics Code			
Telematics Transaction			
GL Account	J05-####-052		

Asset Details

Primary Meter

Multiple Assets, Locations and CIs

Tasks 1 - 2 of 2

Sequence	Task	Summary	Component	Reason for Repair	Warranty?	Route	Route Stop	Qualifications	Status
10	10	ESTABLISH ON TRACK SAFETY PER RPW			N			NONE	COMP
20	20	INSPECT TRACK PER BALT LR STANDARI			N			NONE	COMP

abor Materials Tools Failure Reporting

Labor 1 - 2 of 2

Task	Labor	Approved?	Start Date	Start Time	End Time	Regular Hours	Rate	Warranty?	Qualification Met?
	JBROCKMEYER	<input checked="" type="checkbox"/>	08/06/13	05:00:00	01:00:00	8:00	27.17	N	N/A
	GLAM	<input checked="" type="checkbox"/>	08/06/13	05:00:00	01:00:00	8:00	26.29	N	N/A

Select Labor Select Planned Labor New Row

TRACK INSPECTION REPORTING FORM

me GLAM

Date 8/7/2013

Page / of /

(Please Print)

Watchman Schisler

Inspected From CAMDEN

To Linthicum

W.O Number_ 1172680

	Exception Chain Marker No.		W.O.	Track	Rail	Switch	Codes		Status	Repair
Item	From	To	Number	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
Item	COMMENTS									

Item	COMMENTS
------	----------

NO NEW DEFECTS NOTED IN AREA

Were Switch In the area of Inspected Yes ✓ NO

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?

Yes _____ NO ✓

SPECIAL INSPECTION Yes _____ NO ✓

Reason for special Inspection ?

Track Inspector Signature

Supervisory Certification

u

Quick Reporting (Tr) Bulletins: (1) Go To Reports Start Center Profile Sign Out Help

Find: Select Action

Quick Reporting Specifications

Work Order: 1172680 TEAM TWO - SECT 4: CY/LINT - CM 16S TC Site: LTRAIL

Classification: MTA \ LTRAIL MTA - LTRAIL Status: CLOSE

Asset: Priority: 1

Alias: Work Type: PM

Location: CHAIN_MARK LT Rail Chain Markers Crew:

Work Location: Warranty Situation Present?: N

Work Group: MTA527 Maintenance Alert?: ☐

Work Details

Component: Total Planned Cost: 0.00

Position: Total Actual Cost: 420.64

Reason for Repair: Repair Limit Amount:

Work Accomplished: Reported By: MTACRON

Part Failure: Reported Date: 08/03/13 12:48:30 AM

Parent WO:

Telematics Code:

Telematics Transaction:

GL Account: J05-####-052

Asset Details

Primary Meter

Multiple Assets, Locations and CIs Filter

Tasks Filter 1 - 2 of 2

Sequence	Task	Summary	Component	Reason for Repair	Warranty?	Route	Route Stop	Qualifications	Status
10	10	ESTABLISH ON TRACK SAFETY PER RPW	<input type="text"/>	<input type="text"/>	N			NONE	CLOSE
20	20	INSPECT TRACK PER BALT LR STANDARI	<input type="text"/>	<input type="text"/>	N			NONE	CLOSE

labor Materials Tools Failure Reporting

Labor Filter 1 - 2 of 2

Task	Labor	Approved?	Start Date	Start Time	End Time	Regular Hours	Rate	Warranty?	Qualification Met?
	TSCHISLER	<input checked="" type="checkbox"/>	08/07/13	06:00:00	02:00:00	8:00	26.29	N	N/A
	GLAM	<input checked="" type="checkbox"/>	08/07/13	06:00:00	02:00:00	8:00	26.29	N	N/A

Select Labor Select Planned Labor New Row

Quick Reporting (Tr) Bulletins: (1) Go To Reports Start Center Profile Sign Out Help

Find: Select Action

Quick Reporting Specifications

Work Order: 1193080 TEAM TWO - SECT 5: LINT/CROM - CM 354 Site: LTRAIL

Classification: MTA \ LTRAIL MTA - LTRAIL Status: COMP

Asset: Priority: 1

Alias: Work Type: PM

Location: CHAIN_MARK LT Rail Chain Markers Crew:

Work Location: Warranty Situation Present? N

Work Group: MTA527 Maintenance Alert? ☐

Work Details

Component: Total Planned Cost: 0.00

Position: Total Actual Cost: 427.68

Reason for Repair: Repair Limit Amount:

Work Accomplished: Reported By: MTACRON

Part Failure: Reported Date: 08/23/13 04:01:03 AM

Parent WO:

Telematics Code:

Telematics Transaction:

GL Account: J05-####-052

Asset Details

Primary Meter

Multiple Assets, Locations and CIs Filter Download

Tasks Filter 1 - 2 of 2 Download

Sequence	Task	Summary	Component	Reason for Repair	Warranty?	Route	Route Stop	Qualifications	Status
10	10	ESTABLISH ON TRACK SAFETY PER RPW	<input type="text"/>	<input type="text"/>	N			NONE	COMP
20	20	INSPECT TRACK PER BALT LR STANDARD	<input type="text"/>	<input type="text"/>	N			NONE	COMP

labor Materials Tools Failure Reporting

Labor Filter 1 - 2 of 2 Download

Task	Labor	Approved?	Start Date	Start Time	End Time	Regular Hours	Rate	Warranty?	Qualification Met?
	RNELSON	<input checked="" type="checkbox"/>	08/31/13	06:00:00	02:00:00	8:00	27.17	N	N/A
	WBRYANT	<input checked="" type="checkbox"/>	08/31/13	06:00:00	02:00:00	8:00	26.29	N	N/A

Select Labor Select Planned Labor New Row

TRACK INSPECTION REPORTING FORM

me Follard,
(Please Print)

Date 8-7-2013

Page 2 of 2

✓atchman

Inspected From

W.O Number. 1172683

To

[illegible]

Item	COMMENTS
------	----------

Yard inspection complete
No new defects

Were Switch in the area of Inspected Yes NO

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?

Yes NO

SPECIAL INSPECTION Yes_____ NO

Reason for special Inspection ?

Track Inspector Signature

Supervisory Certification

Quick Reporting (Tr) Bulletins: (1) Go To Reports Start Center Profile Sign Out Help

BMXAA4591E - Status change(s) completed successfully.

Find: Select Action [Icons]

Quick Reporting Specifications

Work Order <input type="text" value="1172683"/> TEAM ONE - SECT 5 - CM 355S/488S AND	Site <input type="text" value="LTRAIL"/>
Classification <input type="text" value="MTA \ LTRAIL"/> <input type="text" value="MTA - LTRAIL"/>	Status <input type="text" value="CLOSE"/>
Asset <input type="text"/>	Priority <input type="text" value="1"/>
Alias <input type="text"/>	Work Type <input type="text" value="PM"/>
Location <input type="text" value="CHAIN_MARK"/> <input type="text" value="LT Rail Chain Markers"/>	Crew <input type="text" value="DAY-A"/>
Work Location <input type="text"/>	Warranty Situation Present? <input type="text" value="N"/>
Work Group <input type="text" value="MTA527"/>	Maintenance Alert? <input type="text"/>

Work Details

Component <input type="text"/>	Total Planned Cost <input type="text" value="0.00"/>
Position <input type="text"/>	Total Actual Cost <input type="text" value="420.64"/>
Reason for Repair <input type="text"/>	Repair Limit Amount <input type="text"/>
Work Accomplished <input type="text"/>	Reported By <input type="text" value="MTACRON"/>
Part Failure <input type="text"/>	Reported Date <input type="text" value="08/03/13 12:48:42 AM"/>
Parent WO <input type="text"/>	
Telematics Code <input type="text"/>	
Telematics Transaction <input type="text"/>	
GL Account <input type="text" value="J05-####-052"/>	

Asset Details

Primary Meter

Multiple Assets, Locations and CIs Filter [Icons] Download [Icons]

Tasks Filter [Icons] 1 - 2 of 2 Download [Icons]

Sequence	Task	Summary	Component	Reason for Repair	Warranty?	Route	Route Stop	Qualifications	Status
10	10	ESTABLISH ON TRACK SAFETY PER RPW			N			NONE	CLOSE
20	20	INSPECT TRACK PER BALT LR STANDARD			N			NONE	CLOSE

New Row

Labor Filter [Icons] 1 - 2 of 2 Download [Icons]

Task	Labor	Approved?	Start Date	Start Time	End Time	Regular Hours	Rate	Warranty?	Qualification Met?
	MPOLLARD	<input checked="" type="checkbox"/>	08/07/13	07:00:00	03:00:00 F	8:00	26.29	N	N/A
	RNELSON1	<input checked="" type="checkbox"/>	08/07/13	07:00:00	03:00:00 F	8:00	26.29	N	N/A

Select Labor **Select Planned Labor** **New Row**

TRACK INSPECTION REPORTING FORM

me

Bollard

Date _____

8-7-2013

Page 1 of 1

7

✓✓atchman

(Please Print)

Nelson

Inspected From

Linthicum

To

Cromwell

W.O Number_

472683

	Exception Chain Marker No.		W.O.	Track	Rail	Switch	Codes		Status	Repair
Item	From	To	Number	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
COMMENTS:										

Item	COMMENTS
------	----------

No new defects noted

Track inspection complete

Were Switch in the area of Inspected Yes NO

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?

Yes_____NO_____

SPECIAL INSPECTION Yes_____ NO

Reason for special Inspection ?

Track Inspector Signature

Track Inspector Signature
Michael Koller

Supervisory Certification

on _____

TRACK INSPECTION REPORTING FORM

me

Pollard.

(Please Print)

Date _____

8-8-2013

Page / of /

Watchman

Nelson

Inspected From

Lotherville

To

Cold Spring

W.O Number_

471623

[illegible]

Item	COMMENTS
------	----------

[illegible]

Were Switch in the area of Inspected Yes ☒ NO

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?

Yes _____ NO _____

SPECIAL INSPECTION Yes_____ NO ✓

Reason for special Inspection ? _____

Track Inspector Signature

Track Inspector Signature *H. Michael K. Coland*

Supervisory Certification

on 1/1/2020

TRACK INSPECTION REPORTING FORM

Name G LAM

Date 8/8/2013

Page / of /

(Please Print)

Watchman Brock Meyer

W.O Number 117268 1171616

Inspected From

HV

To

Luther ville

[illegible]

Item	COMMENTS
------	----------

[illegible]

Were Switch In the area of Inspected Yes ☒ NO ☐

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?

Yes ☐ NO ☒

SPECIAL INSPECTION Yes _____ NO ☒

Reason for special Inspection ?

Track Inspector Signature

Supervisory Certification

TRACK INSPECTION REPORTING FORM

me LAM

Date 8/10/13

Page / of /

(Please Print)

• Watchman

Inspected From

To

W.O Number.

	Exception Chain Marker No.		W.O.	Track	Rail	Switch	Codes		Status	Repair
Item	From	To	Number	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
Item	COMMENTS									

Item	COMMENTS
------	----------

no new Defects found in Area

Were Switch in the area of Inspected Yes 1 NO

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?

Yes _____ NO ✓

SPECIAL INSPECTION Yes_____ NO ✓

Reason for special Inspection ?

Track Inspector Signature

Supervisory Certification

Quick Reporting (Tr) Bulletins: (1) Go To Reports Start Center Profile Sign Out Help

Find: Select Action

Quick Reporting Specifications

Work Order: 1155565 TEAM TWO - SECT 5: LINT/CROM - CM 355 Site: LTRAIL

Classification: MTA \ LTRAIL MTA - LTRAIL Status: CLOSE

Asset: Priority: 1

Alias: Work Type: PM

Location: CHAIN_MARK LT Rail Chain Markers Crew:

Work Location: Warranty Situation Present?: N

Work Group: MTA527 Maintenance Alert?: ☐

Work Details

Component: Total Planned Cost: 0.00

Position: Total Actual Cost: 0.00

Reason for Repair: Repair Limit Amount:

Work Accomplished: Reported By: MTACRON

Part Failure: Reported Date: 07/19/13 12:35:27 AM

Parent WO:

Telematics Code:

Telematics Transaction:

GL Account: J05-####-052

Asset Details

Primary Meter

Multiple Assets, Locations and Cls Filter Download

Tasks Filter 1 of 2 Download

Sequence	Task	Summary	Component	Reason for Repair	Warranty?	Route	Route Stop	Qualifications	Status
10	10	ESTABLISH ON TRACK SAFETY PER RPW	<input type="text"/>	<input type="text"/>	N			NONE	CLOSE
20	20	INSPECT TRACK PER BALT LR STANDAR	<input type="text"/>	<input type="text"/>	N			NONE	CLOSE

Labor Materials Tools Failure Reporting

Labor Filter Download

Task	Labor	Approved?	Start Date	Start Time	End Time	Regular Hours	Rate	Warranty?	Qualification Met?
...No rows to display...									

TRACK INSPECTION REPORTING FORM

Page 1 of 2

1171472

	Exception Chain Marker No.		W.O.	Track	Rail	Switch	Codes		Status	Repair
Item	From	To	Number	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
Item	COMMENTS									

[illegible]

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?

Yes _____ NO ☒

Reason for special Inspection ?

Supervisory Certification

tion

TRACK INSPECTION REPORTING FORM

Name G LAM

Date 8/9/13

Page 2 of 2

(Please Print)

Watchman Schisler

W.O Number 1171472

Inspected From NAVE YD

To _____

[illegible]

Item	COMMENTS
------	----------

[illegible]

Were Switch In the area of Inspected Yes ☒ NO

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?

Yes _____ NO ☒

SPECIAL INSPECTION Yes ☐ NO ☒

Reason for special Inspection ? _____

Track Inspector Signature

Supervisory Certification

on 

Quick Reporting (Tr) Bulletins: (1) Go To Reports Start Center Profile Sign Out Help

Find: Select Action [Icons]

Quick Reporting Specifications

Work Order: 1171472	TEAM TWO - SECT 3 - CM 235N/16S AND	Site: LTRAIL
Classification: MTA \ LTRAIL	MTA - LTRAIL	Status: COMP
Asset: <input type="text"/>	<input type="text"/>	Priority: 1
Alias: <input type="text"/>		Work Type*: PM
Location: CHAIN_MARK	LT Rail Chain Markers	Crew: <input type="text"/>
Work Location: <input type="text"/>	<input type="text"/>	Warranty Situation Present?: N
Work Group*: MTA527		Maintenance Alert? <input type="checkbox"/>

Work Details

Component: <input type="text"/>	Total Planned Cost: 0.00
Position: <input type="text"/>	Total Actual Cost: 420.64
Reason for Repair: <input type="text"/>	Repair Limit Amount: <input type="text"/>
Work Accomplished: <input type="text"/>	Reported By: MTACRON
Part Failure: <input type="text"/>	Reported Date: 08/02/13 12:17:50 AM
Parent WO: <input type="text"/>	
Telematics Code: <input type="text"/>	
Telematics Transaction: <input type="text"/>	
GL Account: J05-####-052	

Asset Details

Primary Meter

Multiple Assets, Locations and CIs Download

Tasks Download

Sequence	Task	Summary	Component	Reason for Repair	Warranty?	Route	Route Stop	Qualifications	Status
10	10	ESTABLISH ON TRACK SAFETY PER RPW	<input type="text"/>	<input type="text"/>	N			NONE	COMP
20	20	INSPECT TRACK PER BALT LR STANDARD	<input type="text"/>	<input type="text"/>	N			NONE	COMP

New Row

bor Materials Tools Failure Reporting

Labor Download

Task	Labor	Approved?	Start Date	Start Time	End Time	Regular Hours	Rate	Warranty?	Qualification Met?
<input type="text"/>	TSCHISLER	<input checked="" type="checkbox"/>	08/09/13	06:00:00	02:00:00	8:00	26.29	N	N/A
<input type="text"/>	GLAM	<input checked="" type="checkbox"/>	08/09/13	06:00:00	02:00:00	8:00	26.29	N	N/A

Select Labor Select Planned Labor New Row

TRACK INSPECTION REPORTING FORM

me

Pollard

Date _____

8-9-2013

Page of

1 of 1

✓✓ watchman

(Please Print)

Nelson

Inspected From

Linthicum

To

Camden yards

W.O Number_

1171559

[illegible]

Item	COMMENTS
------	----------

[illegible]

Were Switch in the area of Inspected Yes ✓ NO

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?

Yes _____ NO ✓

SPECIAL INSPECTION Yes _____ NO ✓

Reason for special Inspection ?

Track Inspector Signature

Track Inspector Signature
Michael L. Ballay

Supervisory Certification

ion

Quick Reporting (Tr) Bulletins: (1) Go To Reports Start Center Profile Sign Out Help

Find: Select Action

Quick Reporting Specifications

Work Order	1171559	TEAM ONE - SECT 4: CY/LINT - CM 16S TC	Site	LTRAIL
Classification	MTA \ LTRAIL	MTA - LTRAIL	Status	CLOSE
Asset			Priority	1
Alias			Work Type	PM
Location	CHAIN_MARK	LT Rail Chain Markers	Crew	
Work Location			Warranty Situation Present?	N
Work Group	MTA527		Maintenance Alert?	

Work Details

Component		Total Planned Cost	0.00
Position		Total Actual Cost	420.64
Reason for Repair		Repair Limit Amount	
Work Accomplished		Reported By	MTACRON
Part Failure		Reported Date	08/02/13 12:22:18 AM
Parent WO			
Telematics Code			
Telematics Transaction			
GL Account	J05-####-052		

Asset Details

Primary Meter

Multiple Assets, Locations and CIs

Tasks 1 - 2 of 2

Sequence	Task	Summary	Component	Reason for Repair	Warranty?	Route	Route Stop	Qualifications	Status
10	10	ESTABLISH ON TRACK SAFETY PER RPW			N			NONE	CLOSE
20	20	INSPECT TRACK PER BALT LR STANDARD			N			NONE	CLOSE

Labor 1 - 2 of 2

Task	Labor	Approved?	Start Date	Start Time	End Time	Regular Hours	Rate	Warranty?	Qualification Met?
	RNELSON1		08/09/13	07:00:00	03:00:00	8:00	26.29	N	N/A
	MPOLLARD		08/09/13	07:00:00	03:00:00	8:00	26.29	N	N/A

Labor

Task		Start Date	08/09/13	Warranty?	N	
Labor	RNELSON1	Richard Nelson	Start Time	07:00:00	Qualification Met?	N/A
Regular Hours	8:00	End Date	08/09/13	Approved?		
Component		End Time	03:00:00	Timer Status		
Position		Rate	26.29	Craft	AREPAIR	
Reason for Repair		Line Cost	210.32	Skill Level		
Work Accomplished		Type	WORK			
Part Failure						
Memo						

Outside Labor

Outside?		Premium Pay Code		Charge Information	
Vendor		Premium Pay Hours		GL Debit Account	J05-####-052
Contract		Premium Pay Rate		GL Credit Account	
Revision		Premium Rate Type		Location	CHAIN_MARK
				Asset	
				Alias	
				Recorded as Received	